



Micro Weather Pro™

Quick Install Guide



Eight Easy Steps

1. Prepare Site
2. Set-up Tripod and Secure Legs to Ground
3. Mount the Enclosure Box (MicroDCP)
4. Ground the MicroDCP
5. Mount the Sensors (*align Wind Direction to North*)
6. Connect the Sensor Cables to the MicroDCP (*match colors*)
7. Connect the RS-232 Cable
8. Turn on the Power



Verify operation with this Hand Held Display

PN 20250024



800-MESOTECH 8:00 a.m. – 5:00 p.m. PT
© 2006 Mesotech International, Inc.
All rights reserved.
Rev 1.2 August 11, 2006